

conservation studio

Responses to Heritage Victoria permit conditions

Her Majesty's Theatre

17 Lydiard Street South, Ballarat 3350 VIC

Prepared for



Date: 20/12/2022 Revision: B

Revision	Date	Comments
А	16/12/2022	Issue for approval by the client
В	20/12/2022	Issue to Heritage Victoria

Disclaimer:

This report is released subject to the following qualifications and conditions:

The document may only be used by named party(s) for the purpose in which it has been commissioned and in accordance with the conditions of engagement.

- · The document is to be reproduced in full.
- The document does not relieve any other party of their responsibilities, liabilities and contractual obligations.
- The content of this document is copyright protected. The copyright of all images, maps and diagrams remains with Conservation Studio Australia P/L or with the photographer/collection as acknowledged and referenced.
- You may not display, print or reproduce any image, map or diagram without the permission of the copyright holder.
- This document excludes the identification of Hazardous Materials including asbestos.
- The findings outlined in this document are based on a visual assessment of the building /structure / place. No invasive investigation has been undertaken.
- This report does not consider any required compliance upgrades associated with the Disability Discrimination Act 1992

Contents

Preamble	1
Permit conditions	1
Condition 3 – Heritage Management Plan	2
Condition 4 – Auditorium chairs storage	3
1.1 Storage methodology	3
1.2 Storage location	3
Condition 5 – Construction set	5
Architectural set – Conservation Studio	5
Structural set – Mark Hodkinson Pty Ltd	7
Services set – JBA Smarter engineering	7
Condition 6 – Minor changes	9
Appendix A – Heritage Management Plar	n 16
Appendix B - Construction set revision C1	. 17
Appendix C – Impact of eastern cladding	deletion 18

Preamble

This report has been prepared on behalf of City of Ballarat in response to the conditions 3, 4, 5 and 6 to Heritage Victoria permit application P35384 (amended) dated 26 April 2022.

Following the permit application dated 10 December 2021 for stage 3 works associated with the accessibility, safety & compliance, and functionality upgrades to Her Majesty's Theatre, Ballarat H0648, the permit has been issued with conditions under s102 of the Act.

This report is submitted for endorsement and outlines the conditions 3, 4, 5 and 6 of the permit application as follows:

- Condition 3 Heritage Management Plan
- Condition 4 Auditorium seat storage
- Condition 5 Construction set
- Condition 6 Minor changes

Permit conditions

- 3. Prior to the commencement of any of the works approved by this permit, a Heritage Management Plan (the Plan) must be provided for endorsement by the Executive Director, Heritage Victoria and once endorsed becomes part of the permit. The Plan must include a sequencing program for the approved works, details of any temporary infrastructure and services required, protection methods for the heritage place during the undertaking of the works, and a work site layout plan.
- 4. Prior to the commencement of any of the works approved by this permit, a final plan addressing the storage methodology and location of the auditorium chairs to be removed and stored is to be provided for endorsement by the Executive Director Heritage Victoria and once endorsed becomes part of the permit.
- 5. Prior to the commencement of any of the works approved by this permit a construction ready set of drawings (including any conservation works) must be submitted for the endorsement of the Executive Director Heritage Victoria and when endorsed becomes part of the permit.
- 6. Should further minor changes in accordance with the intent and approach of the endorsed documentation become necessary, correspondence and supporting documentation must be prepared and lodged for assessment by the Executive Director Heritage Victoria who will advise on the approach to be taken to address these matters.

Condition 3 – Heritage Management Plan

3. Prior to the commencement of any of the works approved by this permit, a Heritage Management Plan (the Plan) must be provided for endorsement by the Executive Director, Heritage Victoria and once endorsed becomes part of the permit. The Plan must include a sequencing program for the approved works, details of any temporary infrastructure and services required, protection methods for the heritage place during the undertaking of the works, and a work site layout plan.

The Heritage Management Plan (the Plan) has been prepared by the Contractor, Nicholson Construction, engaged to complete the project. The Contractor also completed the previous stages 1 and 2.

A site visit was organised on 9 December 2022 with the City of Ballarat, Her Majesty's Theatre staff, Nicholson Construction and Conservation Studio to review the proposal.

In response to the condition, the following clarification was required from the Contractor during the tender.

In line with condition 3 of the Heritage Victoria permit, Contractor is to prepare the Heritage Management Plan (refer to Authority conditions schedule above) against the registered place and in particular any works that could cause damages or harms to the heritage fabrics.

The Plan is to be reviewed with the Principal and the Conservation architect after selection of the preferred tenderer but form part of the tender process.

The Plan is to incorporate the following information but is not limited to:

- 1. Sequencing program for the approved works:
 - a. Include conditions 2, 4 and 5.
- Details of any temporary infrastructure and services required:
 - a. Site establishment.
 - b. Scaffolding, gantry and temporary propping.
 - Lifting of heavy components above the building.
 - d. Protection to maintain the building watertight and weather tight (i.e. Lift 1 shaft through roof).
 - e. Methodology of new services installation.
 - Fixings methodology to avoid / limit impacts to heritage fabrics.

- Protection methods for the heritage place during the undertaking of the works:
 - a. Submission of the dilapidation record.
 - b. Heritage induction to all trades.
 - Protection to heritage fabrics (i.e. urinal in basement B1, stairs and in particular 2b and 4, floors, walls and ceilings).
 - Methodology of demolition (i.e. stair 3, traegerwellblech floor).
 - Methodology of excavation and underpinning.
 - f. Methodology of new opening including temporary propping as required and precaution to limit the impact on the fabric to remain (i.e. floor openings in the auditorium, wall openings to expose bluestone / brick works and hard plaster works).
 - g. Salvaged fabric: recording, dismantling, cleaning, storage and reinstatement as required (i.e. bluestone and brick works, timber floor / ceiling boards, decorative fibre plaster panel to the western elevation of the auditorium).
- Work site layout plan including showing location of the relevant information listed above.

We trust the Plan prepared by Nicholson Construction and attached in Appendix A – Heritage Management Plan responds to condition 3 of the permit.

Condition 4 – Auditorium chairs storage

4. Prior to the commencement of any of the works approved by this permit, a final plan addressing the storage methodology and location of the auditorium chairs to be removed and stored is to be provided for endorsement by the Executive Director Heritage Victoria and once endorsed becomes part of the permit.

The auditorium chairs have been installed as part of the works completed in 2015. During stage 3, it is proposed to carefully remove the chairs to undertake the fire protection works to the balconies, and also to install the temporary closure on the front rows. At the completion of the works, all the chairs will be reinstated except on the front row until the balconies are made structurally compliant.

It is proposed to carefully disconnect the chairs from the floor after recording their location. The removal will be completed in coordination with the technical staff of the theatre used to handling the seats.

Extract from the Plan (section 3.6 - pages 7-8):

Before any works commence, the existing seats that are required to be removed for sprinkler works, will be clearly identified and numbered including taking photographic records of the seats prior to removal and markup drawing will be completed to ensure the seat goes back in the same location once the sprinkler works have been completed.

The temporary closer wall will be installed first to ensure fall protection for the personnel who are completing works in the seating area of the dress circle and balcony levels. [..] Once the wall {meaning temporary closer} has been installed, the seats {in the rest of the balconies} will be carefully removed and stored on site, either in dressing room 2 & 3 or in the orchestra pits. The seats will be stored off the floor and protected with drop sheets.

Once fire service works under the floor have been completed and the floor finishes have been installed the seats will be then reinstall back to their original location and protected with drop sheets.

The existing seating that is not being removed will be covered with a drop sheet to the protect the seats from dust.

1.1 Storage methodology

All chairs will be handled with care by the technical staff of the theatre, or by competent trades to be trained by the technical staff after completion of the "site specific induction" part of the Plan.

All chairs will be laid out off the floor and straight against each other (soft fabric against soft fabric) and entirely covered with tarpaulin or drop sheet.

The location of the numbered chairs will be recorded on the storage rooms to facilitate their reinstatement in the appropriate location.

1.2 Storage location

All chairs are proposed to be stored on site during and after the construction. All storage areas have the same temperature and humidity control as the auditorium.

1.2.1 Storage associated with front row

During construction

Until the structural remediation works are completed on the balustrades, the 68 chairs from the first rows of the balconies will be stored in the orchestra pit part of the auditorium.

After construction

At the completion of the project, several storage areas are proposed, always maintaining the chairs on site as follows:

- Area A Front of House Room 1 Fa.04.
- Area B Hub/administration area Room B2b-10.
- Area D South fire stair area Room B2d.05.

However, the rooms will be reassessed to make sure the temperature and humidity are similar to the auditorium.

1.2.2 Storage associated with fire protection

During the construction, all chairs will be stored in the Back of House – Level B1 – Dressing rooms 2 and 3 (B1c-06 and 09) recently refurbished during the stage 2.

The rooms are fully ventilated with temperature control which will remain equivalent to the auditorium's environmental condition.




Figure 1
Storage area during construction. Storage associated with front row and storage associated with fire protection.




Figure 2 View of the dressing room 2.

Condition 5 - Construction set

5. Prior to the commencement of any of the works approved by this permit a construction ready set of drawings (including any conservation works) must be submitted for the endorsement of the Executive Director Heritage Victoria and when endorsed becomes part of the permit.

We have attached for your consideration the construction set revision C1 including localised conservation works for endorsement. All changes compared to the approved set revision DD2 are listed in Condition 6 – Minor changes.

Day 16

The construction set includes the following sets:

- Architectural set Conservation Studio Revision C1.
- Structural set Mark Hodkinson Pty Ltd Revision C1.
- Services set JBA Smarter engineering Revision CP-A.

Architectural set - Conservation Studio

	Day	Т0
	Month	12
	Year	22
Dwg No.	Drawing Title	
	Series 0 - General	
HA.0.01	Aerial view, drawing register and	C1
	general notes	
	Series 1 - Existing and demolition	
	drawings	
HA.1.01	Basement B2 Plan	C1
HA.1.02	Basement B1 Plan	C1
HA.1.03	Ground Floor Plan & Mezzanine	C1
HA.1.04	First Floor Plan	C1
HA.1.05	Second Floor Plan	C1
HA.1.06	Roof Plan	C1
HA.1.07	Basement B2 Plan – Reflected Ceiling	C1
	Plan	
HA.1.08	Basement B1 Plan – Reflected Ceiling	C1
	Plan	
HA.1.09	Ground Floor Plan & Mezzanine –	C1
	Reflected Ceiling Plan	
HA.1.10	First Floor Plan – Reflected Ceiling	C1
	Plan	
HA.1.11	Second Floor Plan – Reflected Ceiling	C1
	Plan	
HA.1.12	West Facade	C1
HA.1.13	North Facade	C1
HA.1.14	East Facade	C1
HA.1.15	South Facade	C1
HA.1.16	General section West-East Auditorium	C1
	– Internal elevations	
HA.1.17	General section South-North	C1
HA.1.18	Area A – Sections North-South	C1
HA.1.19	Area D — Section West-East	C1
	Series 2 - Proposed drawings	
	General	
HA.2.001	Plans	C1
HA.2.002	East facade	C1
HA.2.003	South facade	C1

	Day	10
	Month	12
	Year	22
Dwg No.	Drawing Title	
	Area A – Front of House	
HA.2.101	Ground floor plan and RCP	C1
HA.2.102	Basement B1 plan and RCP	C1
HA.2.103	First floor plan and RCP	C1
HA.2.104	Second floor plan and RCP	C1
HA.2.105	Roof plan	C1
HA.2.106	West facade	C1
HA.2.107	Section West-East A1	C1
HA.2.108	Section North-South A2	C1
HA.2.109	Section North-South A3	C1
HA.2.110	GF - Internal elevations 1	C1
HA.2.111	GF - Internal elevations 2	C1
HA.2.112	B1 - Internal elevations 1	C1
HA.2.113	B1 - Internal elevations 2	C1
HA.2.114	First and Second floors - Internal	C1
	elevations	
HA.2.115	Joinery - General	C1
HA.2.116	Joinery - Bar	C1
HA.2.117	Joinery - Ticket office	C1
HA.2.118	Joinery - Details 1	C1
HA.2.119	Joinery - Details 2	C1
HA.2.120	Handrail, nosing and TGSI 1/2	C1
HA.2.121	Handrail, nosing and TGSI 2/2	C1
HA.2.122	Joinery - Vanities 1	C1
HA.2.123	Joinery - Vanities 2	C1
	Area E - North Entrance	
HA.2.201	Plans	C1
HA.2.202	Reflected ceiling plans	C1
HA.2.203	Facades north & east	C1
HA.2.204	Sections E1 & E2	C1
HA.2.205	Sections E3 & E4	C1
HA.2.206	Detail - Cladding 1	C1
HA.2.207	Detail - Cladding 2	C1
HA.2.208	Detail - Cladding 3	C1
HA.2.209	Detail - Cladding 4	C1

Day 16

Day	16
Month	12
Year	22

Dwg No.	Drawing Title	
HA.2.210	Detail - Stair 6	C1
HA.2.211	Detail - Stair 5	C1
HA.2.212	Detail - Roof	C1
HA.2.213	Detail - Entry	C1
	Area B - HUB (Basement B2)	
HA.2.301	Basement B2 plan	C1
HA.2.302	Basement B2 RCP	C1
HA.2.303	Basement B2 Elevations 1	C1
HA.2.304	Basement B2 Elevations 2	C1
HA.2.305	Basement B2 Elevations 3	C1
HA.2.306	Basement B2 Elevations 4	C1
HA.2.307	Stair 101 / POD	C1
HA.2.308	Joinery - Details	C1
HA.2.309	Joinery - Vanity	C1
	Area B - HUB (Auditorium)	
HA.2.401	Stalls plan	C1
HA.2.402	Dress circle plan	C1
HA.2.403	Balcony plan	C1
HA.2.404	Stalls plan RCP	C1
HA.2.405	Dress circle plan RCP	C1
HA.2.406	General sections	C1
HA.2.407	North & West elevations	C1
HA.2.408	Balconies – Temporary closer	C1
	Area D — South Fire Stair	
HA.2.501	Plans 1/2	C1
HA.2.502	Plans 2/2	C1
HA.2.503	Reflected Ceiling Plans 1/2	C1
HA.2.504	Reflected Ceiling Plans 2/2	C1
HA.2.505	Section D1 West-East	C1
HA.2.506	Section D2 West-East	C1
HA.2.507	Section D3 to D5 North-South	C1
HA.2.508	Section D6 East-West	C1
HA.2.509	Internal elevations & Details	C1
HA.2.510	Detail – Stair 4 / Ramp 1	C1
	Area C - Back of House	
HA.2.601	Basement B2 Plan	C1
HA.2.602	Basement B2 / Stage RCP	C1
HA.2.603	Basement B2 Internal elevations 1/2	C1
HA.2.604	Note in use	C1
HA.2.605	Basement B1 Plan	C1
HA.2.606	Not in use	C1

	Day	16
	Month	12
	Year	22
Dwg No.	Drawing Title	
HA.2.607	Basement B2 Internal elevations 2/2	C1
	Series 3 - Details	
	General details	
HA.3.001	Wall types	C1
HA.3.002	Ceiling types	C1
HA.3.003	Skirting and cornice types	C1
HA.3.004	General openings	C1
HA.3.005	Lift 1 details	C1
HA.3.006	Lift 2 details	C1
	Doors and windows schedule	
HA.3.101	Standard details	C1
HA.3.102	Area A - Front of House 1	C1
HA.3.103	Area A - Front of House 2	C1
HA.3.104	Area A - Front of House 3	C1
HA.3.105	Area A - Front of House 4	C1
HA.3.106	Area B - Auditorium 1	C1
HA.3.107	Area B - HUB 1 / Auditorium 2	C1
HA.3.108	Area B - HUB 2 / Auditorium 3	C1
HA.3.109	Area B/C - HUB 3 / Back of House 1	C1
HA.3.110	Area D/E - South / North fire stairs 1/1	C1
HA.3.111	Area D/E - South / North fire stairs 2/2	C1
HA.3.112	Area E - North fire stair 3	C1
	Specification	
	Specification Part 1 – General	C1
	Schedule 1 – Floor Finish Schedule	C1
	Schedule 2 – Door Furniture &	C1
	Hardware Schedule	
	Schedule 3 – Handrail, Nosing &	C1
	TGSI schedule	
	Schedule 4 – Sanitary Fittings &	C1
	Fixtures schedule	
	Schedule 5 – Colour and Material	C1
	schedule	
	Schedule 6 – Light Fittings	C1
	schedule 7 Signago eshadula	
	Schedule 7 – Signage schedule	C1
	Specification Part 2 – Conservation	C1
	Schedule 1 – Conservation works	C1
	Boards Pender begred	C1
	Render board	C1
	Finish board	C1

Structural set – Mark Hodkinson Pty Ltd

Day	16	
Month	12	
Year	22	
notes	C1	

Drawing Title	
Drawing schedule and general notes	C1
Basement B2 Plan	C1
Basement B1 Plan	C1
Ground Floor Plan	C1
First Floor Plan	C1
Second Floor Plan	C1
Roof Plan	C1
Part Plans	C1
B2 Part Plan	C1
Part Plans	C1
Part Plans	C1
Plans	C1
North Entrance Plans	C1
	Drawing schedule and general notes Basement B2 Plan Basement B1 Plan Ground Floor Plan First Floor Plan Second Floor Plan Roof Plan Part Plans B2 Part Plan Part Plans Part Plans Part Plans Plans Plans Plans

	Day	16
	Month	12
	Year	22
Dwg No.	Drawing Title	
S14	North Entrance Plans	C1
S15	Part Plans	C1
S16	Lift Details	C1
S17	North Stair Precast	C1
S18	North Stair Details	C1
S19	North Stair Details	C1
S20	North Stair Details	C1
S21	Balustrade Details	C1
S22	Details	C1
S23	Details	C1
S24	Details	C1
S25	Details	C1

Services set – JBA Smarter engineering

Day 12-13 19-20 Month 12 Year 22

Dwg No.	Drawing Title	
	Electrical services	
E01	Cover	C-PA
E02	General Notes & Legend	C-PA
E03	Basement 2 - Existing – Demolition	C-PA
E04	Basement 2 - Proposed Power,	C-PB
	Communication & Security Layout	
E05	Basement 2 - Proposed Lighting Layout	C-PA
E06	Basement 1 - Existing – Demolition	C-PA
E07	Basement 1 - Proposed Power,	C-PA
	Communications & Security Layout	
E08	Basement 1 - Proposed Lighting Layout	C-PA
E09	Ground Floor - Existing – Demolition	C-PA
E10	Ground Floor - Proposed Power,	C-PA
	Communication & Security Layout	
E11	Ground Floor - Proposed Lighting	C-PB
	Layout	
E12	First Floor - Existing – Demolition	C-PA
E13	First Floor - Proposed Power,	C-PA
	Communication & Security Layout	
E14	First Floor - Proposed Lighting Layout	C-PA
E15	Second Floor - Existing – Demolition	C-PA
E16	Second Floor – Proposed Power,	C-PA
	Communication & Security Layout	
E17	Second Floor - Proposed Lighting	C-PA
	Layout	
E18	Electrical Reticulation Schematic	C-PA

Day 12-13 19-20 Month 12 Year 22
19-20

	Teur	22
Dwg No.	Drawing Title	
E19	Communication Reticulation Schematic	C-PA
	Project specification — Electrical	C-PA
	Mechanical services	C-PA
M01	Cover	C-PA
M02	General Notes and Legend	C-PA
M03	Basement 2 Existing – Demolition	C-PB
M04	Basement 2 – Proposed Ventilation and	C-PB
	AC Layout	
M05	Basement 1 Existing – Demolition	C-PA
M06	Basement 1 – Proposed Ventilation	C-PA
	Layout	
M07	Ground Floor Existing – Demolition	C-PA
M08	Ground Floor – Proposed Ventilation &	C-PA
	AC Layout	
M09	First Floor Existing – Demolition	C-PA
M10	First Floor – Proposed Ventilation	C-PA
	Layout	
M11	Second Floor Existing – Demolition	C-PA
M12	Second Floor – Proposed Ventilation	C-PA
	Layout	
M13	Roof – Proposed Ventilation Layout	C-PA
M14	Equipment Schedule	C-PA
	Project specification – Mechanical	C-PA
	Fire services	
F01	Cover	C-PA
F02	General Notes and Legend	C-PB

Day 12-13 19-20 Month 12 Year 22

Dwg No.	Drawing Title	
F03	Basement 2 - Existing— Demolition	C-PA
F04	Basement 2 - Proposed Layout	C-PA
F05	Basement 1 - Existing– Demolition	C-PA
F06	Basement 1 - Proposed Layout	C-PB
F07	Ground Floor - Existing - Demolition	C-PA
F08	Ground Floor - Proposed Layout	C-PA
F09	First Floor - Existing- Demolition	C-PA
F10	First Floor - Proposed Layout	C-PA
F11	Second Floor – Existing – Demolition	C-PA
F12	Second Floor – Proposed Layout	C-PA
F13	Roof Plan Fire Services Layout	C-PA
F14	Details & Schematic	C-PA
	Project specification – Fire	C-PA
	Hydraulic services	
H01	Cover	C-PA
H02	General Notes and Legend	C-PA
H03	Basement 2 – Existing – Demolition	C-PA
H04	Basement 2 - Proposed Water	C-PA
H05	Basement 2 - Proposed Sewer	C-PA

	D	10.10
	Day	12-13
		19-20
	Month	12
	Year	22
Dwg No.	Drawing Title	
H06	Basement 1 – Existing – Demolition	C-PA
H07	Basement 1 - Proposed Water	C-PA
H08	Basement 1 - Proposed Sewer	C-PA
H09	Ground Floor – Existing – Demolition	C-PA
H10	Ground Floor – Proposed Water	C-PA
H11	Ground Floor - Proposed Sewer	C-PA
H12	First Floor – Existing – Demolition	C-PA
H13	First Floor - Proposed Water	C-PA
H14	First Floor - Proposed Sewer	C-PA
H15	Second Floor – Existing – Demolition	C-PA
H16	Second Floor - Proposed Water	C-PA
H17	Second Floor - Proposed Sewer	C-PA
H18	Roof drainage roof plan	C-PA
H19	Roof drainage elevation detail	C-PA
H20	Details	C-PA
	Project specification – Hydraulic	C-PB
	Vertical transportation services	
	Project specification – Vertical	C-PB
	transportation	

Condition 6 – Minor changes

6. Should further minor changes in accordance with the intent and approach of the endorsed documentation become necessary, correspondence and supporting documentation must be prepared and lodged for assessment by the Executive Director Heritage Victoria who will advise on the approach to be taken to address these matters.

For clarity, part of the contingency works providing better accessibility and compliance works are proposed to proceed. These works have been approved by Heritage Victoria as part of the current permit. The drawings on the documentation set C1 (HA.1.01, HA.1.07, HA.2.001, and series 2.6 – Back of House) have been updated taking into account the following works:

- Ramp 2 and all associated works to the Back of House.
- Extend dressing room 11 of the Back of House to the redundant corridor 7.
- Handrail, nosing and tactile indicator of the stairs 20, 21 included.

In response to the condition 6, we provide the following information with the supporting documentation based on revision C1.

Minor changes	Supporting information	Drawing
General		
Additional compliant signage as follows:		
Front façade on Lydiard Street 1 fire protection sign next to the southern entrance: fire block plan, hose reel signage and performance solution signage. 2 DDA entrance signs to the main entrance and to the southern entrance.	The fire protection signage is a requirement from the Fire Rescue Victoria (regulation 129), and the DDA signage from the AS1468. The finishes have been selected to be sympathetic to the heritage fabric. The signages are offset and screw fixed to the rendered façade. The location takes into account the architecture and details of the facade.	HA.2.106
East façade 3 fire protection signs on or next to the fire hydrant and sprinkler booster and quad feed hydrants: hydrant and sprinkler booster signage, fire block plan, hose reel signage and performance solution signage.	The fire protection signage is a requirement from the Fire Rescue Victoria (regulation 129). The finishes have been selected to be sympathetic to the heritage fabric. The signage is offset and screw fixed to the façade. The location will be finalised on site with the preference to fix into the joint of the bluestone work as much as achievable.	HA.2.002
Stage 1 fire protection sign next to the existing sliding door connecting with the Props Bay (GFd.02)	The fire protection lettering is a requirement from the Fire Rescue Victoria (regulation 129). Selfadhesive vinyl lettering will be applied on the painted wall adjacent to the sliding door. The lettering has no impact on the heritage fabric and could be removed at any time.	HA.2.501
Value management as follows:		
Change of finish from black powder coating to galvanised on handrail HR5 to stair 4 and ramp 1.	The change of finish in the south fire stair (stair 4 and ramp 1) has limited visual impact from black to a dark grey colour (galvanised natural finish).	HA.2.510
Area A – Front of House		
Increase height of the new opening from the future ticket office (GFa.01) to the office (GFa.04)	The increase of height allows to provide natural ventilation to the office (GFa.04). Visually, the change is concealed by the new joinery of the ticket office (no change in design).	HA.1.18 HA.2.110/6


Minor changes	Supporting information	Drawing
Timber ceiling on the basement B1 – corridor 1 (B1a.02) replaced by plasterboard ceiling.	The material replacement is a requirement of the Fire Engineering Report and BCA to have non-combustible material in this space. The replacement with flat surface like the plasterboard is a positive outcome as it will retain	HA.2.102 HA.2.108 HA.2.112
	the same aspect of the existing space and the adjacent co-visible spaces (stair 2a as exposed concrete slab).	
Delete Steel Framed windows Nwa.01, Nwa.02, Nwa.03, Nwa.04 on the basement B1 to provide privacy	The new steel framed windows installed in the lightwell are approved as part of the current permit. Due to budget constraint, they have been removed from the project. The lightwell will remain visible into the amenities as currently.	HA.2.102/01 HA.2.112 HA.2.113 HA.3.105
The livery rooms have been replaced by a large storage room.	The current configuration dates to the 1990s restoration works by Clive Lucas & Partners. None of the fabric nor the flow of the space represents original or significant fabric, nor does it embody or express cultural heritage value of the Theatre.	HA.2.102 HA.2.109 HA.2.113/9 to 20
	The changes of use from livery room (relocated on the area B – HUB / Administration) provide a better outcome by re-exposing the heritage fabric of the peripheral walls.	
	Note: The relocation of an early timber panel door providing a positive outcome to the perception from the stair is maintained.	
Consolidation of the stair 2b 4 th flight dimensioned to worst case scenario with 250 PFC below treads.	The reinforcement is still to be confirmed following the demolition of the stair 3. One of the demolished treads is to be tested to confirm the stone capacity.	HA.2.103 HA.2.109 HA.2.120/7
	In line with the HIS (p. 59), the proposed reinforcement (worst case scenario) is to be maintained exposed and painted to match adjacent colour to reduce the visual impact.	HA.2.121/9
Approved new extension of the safety access on the roof from current walkway to lift is cancelled.	The cancelation maintains the current configuration.	HA.2.105
Redesign of the upper bay windows of the ticket office.	Minor changes of the configuration of the front ticket office to include steel framing concealed by timber board finishes. The finishes remain the same.	HA.2.117 HA.2.119
Area B – HUB / Administration		
Demolition existing / new partition and door around the organ room 3 (B2b.13)	Replacement of non-original partition and door with new FR partition and door in accordance with the Fire Engineering Report. No change of location or design.	HA.1.01

Minor changes	Supporting information	Drawing
Update showing the services into the basement B2, including additional storage for Fan Coil Unit (FCU) in corridor 4 (B2b.13)	All the design is based on re-exposing the 1874 timber framing and floorboards supporting the stalls and avoid any penetrations through. The FCU has been located at floor level to avoid penetration through the 1874 floorboards. The equipment is concealed in a new storage room. The services and in particular the mechanical duct works require in minimum location the removal of non-structural cross brassing to allow new ductwork to run between joists. The removal of these cross bracing is limited to areas concealed behind a suspended ceiling where the relocation of the ductwork is not achievable. The fabrics are salvaged to be re-used were missing in exposed areas.	HA.2.302 HA.2.304 HA.2.305 HA.2.306
Area B — Auditorium		
Additional removal / reinstatement of floor into the dress circle and balcony levels.	The sprinkler protection of the balconies has been approved as part of the safety and protection works including the methodology to install fire pipe works located into the void. In order to install the concealed pipe works at the rear, additional access is required from the top. The works will include the removal of recent finishes (vinyl and carpet), the careful dismantling and reinstatement of the timber board similar to the current approved methodology, and will include replacing section of the carpet and vinyl finishes installed in 2015.	HA.1.04 HA.1.05 HA.2.402 HA.2.403 HA.2.405
Update of the mechanical services into the female amenities to provide fresh air by providing grilles between the spaces.	The internal amenities have been refurbished to the 1990s restoration works by Clive Lucas & Partners. The ventilation system being non-compliant, new grilles are proposed on non-original wall and suspended ceiling with limited visual impact. In the auditorium, two grilles of 120 x 400 mm are located at the rear of the non-original mechanical aedicule at the back of the space. The location is discrete, and the grilles reused the sympathetic design provided along the project. From the stage and the balcony level, the grilles are not visible to the public.	HA.2.402 HA.2.403 HA.2.407/02 HA.3.002/10 and 11
Remove redundant exit sign above door (XDb.12) to lift 1 lobby (stair 3 demolished) installed during stage 2 works on the balcony level – west elevation.	The current exit sign was installed during the stage 2. Now that the door is not a fire exit, the non- original signage is to be made redundant in accordance with the Fire Engineering Report.	HA.1.16 HA.2.406/02 HA.2.407/01

Minor changes	Supporting information	Drawing
	The hard plaster work is to be made good and the whole panel is to be repainted to match existing colour scheme using same paint system, colour and finish.	
Area D — South fire stair		
Underpinning upstand	Where the floor levels of the adjacent property are above the internal floor level of the theatre, structural upstands are required to avoid potential water infiltration. The upstands are against the original wall with no damage to the heritage fabric.	HA.2.501/01 HA.2.507/01 and 03 S11 S22
Traegerwellblech floor removal / reinstatement	To complete the approved opening between the tech. room 3 (B1d.03) and the Props Bay (GFd.02), the careful removal of the corrugated sheet is required and has been documented accordingly. The remaining section of the corrugated sheet will be reinstated.	HA.1.07 HA.2.503/02 HA.2.509/09, 10
Additional handrail to ramp 1 (entrance 3).	A second handrail fixed into the new concrete ramp is required for compliance with the AS1648. The handrail will match the approved handrail type HR5 and will have limited visual impact.	HA.2.501 HA.2.510
Simplification of the Props Bay area (GFd.02)	The approved proposed storage room reducing the Props Bay area has been removed to provide a better functionality to the space. The deletion of the partitioning provides a better outcome to the space reinstating the existing volume.	HA.2.501/03 HA.2.506 HA.2.508
Demolition of existing door / new door NDd.14 between the Props Bay (GFd.02) and the Ante green room (GFd.04).	Replacement of non-original door with new compliant FR door in accordance with the Fire Engineering Report. New door to match approved doors NDd.08 and 09 in the same room (Ante green room) providing compliant access and design consistency.	HA.1.03 HA.2.501
Deletion of approved proposed door	The new opening between the Melba room (1Fd.01) and the storage room (1Fd.02) has been approved. For a better functionality of the theatre, it is proposed to maintain the new opening but delete the door. Both rooms are used as storage and the deletion of the door will have no visual impact.	HA.2.502/1
Simplification of the storage room (1Fd.02)	The approved proposed archive room reducing the storage room area has been removed to provide a better functionality to the space. The deletion of the partitioning provides a better outcome to the space reinstating the existing volume.	HA.2.501/03 HA.2.506 HA.2.508

Minor changes Supporting information Drawing Replacement of modern vent grille and The heritage door and the existing grille are HA.2.504/01 protection of the heritage door of the Melba located in a fire compartment wall based on the room (1Fd.01) Fire Engineering Report. The existing grille does not provide any fire protection and is proposed to be replaced with a similar grille including a fire damper. The retention of the heritage door located in a fire compartment wall requires the installation of sprinkler head above which is in accordance with the current fire design and approved HIS. Fire protection of the opening between the The opening is located in a fire compartment wall HA.2.504/01 stage and the Props Bay (GFd.02) between the stage and the south fire stair area HA.3.111 requiring the protection of a fire curtain based on (NDd.07) the requirements of the Fire Engineering Report. The fire curtain is a discrete solution with the system installed in a head box located at the top on the Props Bay side. Deletion of the limewash in the south fire stair Due to budget constraints, it is proposed to retain HA.505 to (stair 4) the existing paint finish on the existing walls and HA.509 not paint the new blockwork walls. The conservation works to the bluestone and brick works (replacement of deteriorated bricks and localised repointing) is retained.

Minor changes	Supporting information	Drawing
	This solution will maintain the status quo in the space retaining the original or early limewash finish.	
Area E — North stairs		
Coring hole into north façade to the voids of the auditorium balconies for fire protection services.	The fire protection of the auditorium balconies is via the north fire stair 5. The coring is through sections of buttresses to be removed which will be clearly distinct from the original façade.	HA.1.13 HA.1.16
Provision of an enclosure to the upper landing of the auditorium stair (stair 6).	The enclosure of the landing is to avoid littering and anti-social behaviour which in the extreme circumstances could be a risk for the heritage place. The enclosure in opened position during the show has similar design of the approved works and is fully concealed. The enclosure in closed position has similar finish of the internal cladding and maintains the intent	HA.2.201 HA.2.206/2, 3 and 4
Deletion of one handrail to the stair 5.	The cancelation of the approved works allows to reduce the impact of the fixing into the north façade which is a positive outcome.	HA.2.201
Deletion of the eastern decorative perforated cladding of the new fire stair 5 and associated light fitting.	The eastern cladding is along the boundary of the adjoining property, and any future development of the current private carpark could potentially hide this face of the new fire stair.	HA.2.201 HA.2.203/02 HA.2.206/01 HA.2.207/01
	Due to budget constraint, it is proposed to delete this cladding and keep the precast panels exposed. This eastern elevation will have limited visual impact from the public space of Sturt and Camp Streets (north side), and almost none from Lewis and Little Bridge Streets (east side) as showing in the Appendix C – Impact of eastern cladding deletion. Note: The cladding on Unicorn Lane is maintained with the same design, material and finish.	Render board



Additional drawings have been added to the documentation set based on the proposed and approved as follows:

Additional / not in use drawings	Comments
HA.2.122 and HA.2.123	Detail of the vanities in line with approved design, materials, colours and finishes.
HA.2.213	Detail of Unicorn Lane finishes (public area sitting outside the registration).
HA.2.307/04, 05 and 06	Detail of the office pod typical elevation in the HUB / administration area in line with approved design, materials, colours and finishes.
HA.2.308	Detail of the kitchenette and Royal South Street Society ticket counter.
HA.2.309	Detail of the vanities in line with approved design, materials, colours and finishes.
HA.2.509/9 to 15	Detail of the guardrail around new opening and balustrade landing in line with approved design, materials, colours and finishes.
HA.2.510	Detail of the handrail HR5 with galvanised finish instead of powder coated finish.

Based on the above, we consider that the changes listed above are in accordance with the intent and approach of the endorsed permit, and have no detrimental impacts to cultural heritage significance. On this basis, we respectfully seeking that endorsement of this condition.

Appendix A – Heritage Management Plan

Appendix B - Construction set revision C1

- Architectural set Conservation Studio Revision C1.
- Structural set Mark Hodkinson Pty Ltd Revision C1.
- Services set JBA Smarter engineering Revision CP-A / CP-B.

Appendix C – Impact of eastern cladding deletion





Figure 4
Significant views of the north fire stairs from close public spaces.



17 Lyclard St-S

Figure 5
Angle of the photography.

Figure 6
Photograph from Sturt Street. The eastern elevation of the north stair is not visible, hidden by the façade along Strut Street.



Figure 7

Photograph from Camp Street. The top of the north stair is visible including the eastern elevation with some limitation due to the angle.



Figure 9 Detail of the photograph above with north fire stair on the background (eastern façade in pink).



Figure 8
Angle of the photography.



Figure 10
Photograph from Sturt Street. Her Majesty's theatre is not visible.




Figure 12
Photograph from Sturt Street. The rear of Her Majesty's theatre is visible only.



Figure 11Angle of the photography (green top left and grey bottom left).



Figure 13
Photograph from Lewis Street. The rear of Her Majesty's theatre is visible.

Figure 14 Angle of the photography



Figure 15
Detail of the photograph above. The north fire stair is discernible between the façade of the theatre and the rear of the Ballaarat Mechanics Institute (eastern façade in pink).